

2022 MICHIGAN SKILLS USA CHAMPIONSHIPS

1 of 6

glasses) with side shields or safety goggles that meet OSHA Z87.1.

WELDING SMAW, GMAW, GTAW, OFW, OA TASKS & MATERIAL



Purpose:

To evaluate each contestant's preparation for employment and recognize outstanding performance

HIGH SCHOOL:

First, refer to General Regulations.

General:

CONTEST LOCATION:

Washtenaw Community College
4800 E Huron River Dr.
Ann Arbor, MI, US
(734) 973-3300
<https://www.wccnet.edu/>

RESUME:

Each student must submit a one-page printed resume before the contest start at the contest site (present to contest coordinator, not judges). The resume is no longer submitted online. This is the only time that resumes can be turned in. Failure to do so will result in a 10-point penalty.

Clothing Requirement

1. Required 100 percent cotton, fire resistant work pants, protective welder's clothing including welder's hat or skullcap, leather cape with sleeves or fire-resistant welding coat or sleeves, leather gauntlet welding gloves (for other than GTAW), leather welding gloves for GTAW, high-top (6" minimum height) leather shoes and welder's helmet. All outer clothing must be fire-resistant. Industrial quality safety glasses (No tinted safety

Eligibility

Open to active Skills USA members enrolled in programs with welding as the occupational objective.

Equipment and Materials:

1. Supplied by the technical committee:
 1. All necessary welding equipment and materials
 2. All instructions and procedure sheets with drawings
 3. All necessary information and furnishings for judges and technical committee
2. Supplied by the **contestant**:
 - a. Hearing and/or ear protection
 - b. Welding helmet with appropriate filter plate/lens and protective cover plate/lens for the arc process(s) being performed.
 - c. Welding helmet/face shield/goggles with appropriate #5/#7 filter plate/lens and protective cover plate/lens for OFC. (Safety glasses must be able to be worn underneath.)
 - d. No external filler metals.
 - e. Spare spatter and filter lenses/plates for arc welding helmet and oxyacetylene goggles
 - f. Calculator
 - g. Lead pencil and/or ballpoint pen
 - h. Soap stone with holder
 - i. Scribe with magnet
 - j. Combination square set
 - k. Steel tape measure
 - l. Fillet weld gauge
 - m. 16-ounce ball peen hammer
 - n. Center punch
 - o. 6-inch side cutting pliers or diagonal cutting pliers
 - p. 6-inch standard slip lock pliers
 - q. Chipping hammer with or without wire brush
 - r. Stainless steel wire brush
 - s. Tungsten GTAW 3/32 or 1/8 electrodes for DC- + AC welding - **pre-sharpened (can be re-sharpened)**. Contestant should bring multiple sharpened Tungsens.
 - t. Flat or Half Round, Bastard cut type- Metal Hand File- 12" - 14" length.
 - u. 2 - vise grip type pliers
 - v. 1 page resume
 - w. No gas lenses allowed!

Specific Rules for Contest Participants

1. Contestants must correctly use the welding equipment during the contest. The contest chairperson or contest coordinator may *stop* a contestant at any section of the contest if they deem a contestant's manner to be hazardous to either themselves or others. Such stoppage shall disqualify the participant for that section of the contest. If the contestant is warned a second time, he or she will be disqualified as a contest+++ participant.
2. Contestants will be assigned a contest number for use during the welding contest. The contest judges will know the contestants by their assigned number only.
3. While the contest is in progress, there shall be no communication between the contestants or between the contestants and anyone else except as directed by a judge, contest coordinator or contest chairperson.
4. The welding contest will be of a performance nature.
5. All terms and definitions and welding symbols will be in accordance with the current editions of ANSI/AWSA3.0 (Terms and Definitions) and ANSI/AWSA2.4 (Symbols).
6. Time limits will be established on the contest procedure sheets for all segments of the test.
7. Evaluation of the completed project will be judged visually. Non-destructive and/or destructive tests may be used to complete the project evaluation.
8. Welding and cutting operation instructions will be specified in drawings and procedure sheets provided to the contestants.
9. Drawings/prints will be provided at the day of competition. Drawings must be returned in after the project is welded complete.
10. Reference - base metal may include, but is not limited to Mild Steel, Stainless Steel, and Aluminum.
11. No cell phones or cameras allowed in the welding lab.

Scope of the Contest

1. Contestants will demonstrate their ability to perform jobs and skills selected from the following list of competencies as determined by the Skills USA Welding Technical Committee.
 - a. **Safety**
 1. Demonstrate personal safety including PPE.
 2. Demonstrate general shop safety.
 3. Demonstrate gas, electrical and chemical safety.
 4. Demonstrate knowledge of proper actions to be taken in an emergency.
 - b. **Measurements**
 1. Identify basic metal working tools used in measuring.
 2. Use visual measuring tools to accurate of 1/32 of an inch.
 3. Employ the components of a combination square set.
 4. Use layout and marking tools as required.
 - c. **Blueprint Reading**
 1. Use information found in the information block of the drawing.
 2. Read and understand three-dimensional drawings.
 3. Identify the basic views used in blueprints including assembly, detail and fit-up drawings.
 4. Identify common types of lines, abbreviations and symbols in accordance with national drawing standards -ANSI.
 5. Identify basic welding symbols and components of a symbol (such as arrow, reference line, tail, size or length) in accordance with the national welding symbols standards - AWS.
 - d. **Shielded Metal Arc Welding (SMAW)**
 1. I/O Demonstrate safety procedures for SMAW.
 2. I/O Demonstrate the ability to correctly set up SMAW power sources, related welding equipment, and do basic process and equipment troubleshooting.
 3. I/O Correctly identify base metal prior to welding.
 4. I/O Set up and shut down equipment.

I = Individual Competition
O = Overall Competition

5. **I/O** Select the correct type of filler metal and size of electrode based on the base material (1/8-inch to 1/2" thickness).
 6. **I/O** Prepare base material for welding.
 7. **I/O** Start, stop and restart stringer beads on the base material in the flat, horizontal, vertical up and down and overhead positions.
 8. **I/O** Weld a lap joint with a single pass and multi pass, fillet weld on the base material in flat, horizontal, vertical up and down and overhead positions.
 9. **I/O** Weld a T-joint with a single pass, fillet weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 10. **I/O** Weld a T-joint with a multiple pass, fillet weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 11. **I/O** Weld a butt joint with a single pass, square groove weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 12. **I/O** Weld a butt joint with a single pass, V-groove weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 13. **I/O** Weld a butt joint with a partial joint penetration, single pass, double V-groove weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 14. **I/O** Weld a butt joint with a multiple pass, double groove weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 15. **O** Weld 2 inch through 6 inch diameter, schedule 40, pipe, single/multiple pass V-groove weld in the 2G position. Also, fillet weld in the 2F and 5F positions.
 16. **I/O** Weld a plug weld in the flat position
- e. Gas Metal Arc Welding (GMAW)**
1. **I/O** Demonstrate correct safety procedures for GMAW.
 2. **I/O** Demonstrate ability to correctly set up GMAW power sources, related welding equipment, and do basic process and equipment troubleshooting.
 3. **I/O** Correctly identify base metal prior to welding.
 4. **I/O** Set up and shut down equipment.
 5. **I/O** For the electrode being used, be able to select correct, wire feed speed and voltage based on the material (14ga to 3/8-inch thickness).
6. **I/O** Prepare the base material for welding.
 7. **I/O** Start, stop and restart stringer beads on the base material in the flat, horizontal, vertical up and down and overhead positions.
 8. **I/O** Weld a lap joint with a single pass and multi pass fillet weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 9. **I/O** Weld a T-joint with a single pass and multi pass fillet weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 10. **I/O** Weld a butt joint with a single pass, square groove weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 11. **I/O** Weld a butt joint with a single pass and multi pass V-groove weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 12. **I/O** Weld a butt joint with complete joint penetration, multiple pass, double V-groove weld on the base material in the flat, horizontal, vertical up and down and overhead positions.
 13. **O** Weld 2-inch through 6-inch diameter schedule 40, and thinner carbon steel pipe, single/multiple pass V-groove weld in the 2G position. Also, fillet welds in the 2F and 5F positions.
 14. **I/O** Weld a plug weld in the flat position.
- f. Flux Cored Arc Welding (FCAW)**
1. **O** Weld fillet and groove welds in the flat, horizontal, vertical and overhead positions.
- g. Gas Tungsten Arc Welding (GTAW)**
1. **I/O** Demonstrate safety procedures for GTAW.
 2. **I/O** Demonstrate ability to correctly set up GTAW power sources, related welding equipment, and do basic process and equipment troubleshooting.
 3. **I/O** Correctly identify base metal prior to welding.
 4. **I/O** Set up and shut down equipment for welding of the base material
 5. **I/O** Select the correct size and type of tungsten and/or filler material for the base material (1/16-inch to 1/4-inch thickness).
 6. **I/O** Prepare the base material for welding.
 7. **I/O** Start, stop and restart stringer beads on the base material in the flat, horizontal, vertical up and overhead positions.
 8. **I/O** Weld a lap joint with a single pass, fillet weld on the base material in flat, horizontal, vertical up, and overhead positions.

I = Individual Competition

O = Overall Competition

9. **I/O** Weld a T-joint with a single pass fillet weld on the base material in the flat, horizontal, vertical up, and overhead positions.
10. **I/O** Weld a butt joint with a single pass, square groove on the base material in the flat, horizontal, vertical up, and overhead positions.
11. **I/O** Weld a butt joint with a single pass and multi pass, V-groove weld on the base material in the flat, horizontal, vertical up, and overhead positions.
12. **I/O** Weld a butt joint with a multiple pass, V-groove weld on the base material in the flat, horizontal, vertical up, and overhead positions.
13. **I/O** Weld a butt joint with complete joint penetration, multiple pass, double V-groove weld on the base material in the flat, horizontal, vertical up, and overhead positions.
14. **O** Weld 2-inch through 4-inch diameter, schedule 40 and thinner, pipe, single/multiple pass V-groove weld in the 2G position. Also, fillet welds in the 2F and 5F positions.

h. **Oxygen Fuel Cutting (OFC)**

1. **I/O** Demonstrate safety procedures for OFC.
2. **I/O** demonstrates ability to correctly set up OAC equipment for cutting and do basic process troubleshooting.
3. **I/O** correctly identifies base metal prior to cutting.
4. **I/O** Set up and shut down equipment for cutting carbon steel plate.
5. **I/O** Select correct tip size and gas pressure for cutting carbon steel plate (1/4-inch to 1/2-inch thickness).
6. **I/O** Prepare carbon steel for cutting.
7. **I/O** Cutting operations will be specified in drawings and procedure sheets provided to the contestants.
8. **I/O** Properly light, adjust the flame, and shut down the OFC equipment.
9. **I/O** Use a straight edge and soaps stone for laying out the prescribed pattern.
10. **I/O** Make a square cut on carbon steel in flat, horizontal and vertical positions.
11. **I/O** Make a bevel cut (45-degree angle) on carbon steel plate in the flat, horizontal and vertical positions.
12. **I/O** Pierce a hole in carbon steel in the flat, horizontal and vertical position.
13. **I/O** Make a cut on carbon steel pipe in flat, horizontal, and vertical positions.
14. **No cutting guides allowed**

i. **Oxygen Acetylene Welding**

1. **I** Demonstrate the ability to correctly set up OAW equipment for gas welding and do basic process troubleshooting.
2. **I** Correctly identify base metal prior to welding.
3. **I** Select correct tip size and gas pressures for joining carbon steel plate (1/16 inch to 1/4 inch thickness).
4. **I** Demonstrate the ability to weld a butt joint in flat, horizontal, vertical or overhead positions.
5. **I** Demonstrate the ability to weld a fillet weld in flat, horizontal, vertical or overhead positions.

2. **Judging Criteria**

The contestant will be evaluated on the competencies based on the following rating system. The technical committee according to the difficulty of the assigned task will establish point values for each item. Final judging of the welded projects will be evaluated using the following:

a. **Visual Inspection Criteria:**

1. Dimensional accuracy, including distortion. Reference the notes concerning the allowable tolerances on the print
2. Conformity to drawing requirements including determination of whether all welds have been completed and whether the finished welds conform to the required size and contour.
3. Visual examination of the welds for:
 - i. Cracks
 - ii. Undercut
 - iii. Overlap
 - iv. Crater fill
 - v. Spatter
 - vi. Arc strikes
 - vii. Porosity
 - viii. Convexity and reinforcement
 - ix. Tungsten inclusions
 - x. Inadequate joint penetration
 - xi. Surface irregularities
 - xii. Other irregularities

b. Welding equipment may be obtained from a variety of manufacturers and may include transformers, rectifiers and/or inverters.

c. Filler metals will be compatible with the metals being welded and will be detailed on the contest procedure sheet. Instructions to the contestants will define more specifically the filler metals that may be used. Below is a suggested list of electrodes and filler metal types and sizes:

1. Shielded Metal Arc
 - i. E 6010 - 1/8-inch diameter
 - ii. E7018 - 3/32-inch, 1/8 inch diameter

I = Individual Competition

O = Overall Competition

2. Gas Metal Arc
 - i. E70S-3 (or -6) .035 diameter (75% Ar 25% CO2 Shielding Gas)
 3. Gas Tungsten Arc
 - i. 3/32-inch, 1/8-inch diameter
 - ii. ER70-2 - 1/16-inch - 1/8-inch diameter
 - iii. ER4043 - 3/32-inch and 1/8-inch diameter
 - iv. ER308L - 1/16-inch, 3/32-inch diameter
 4. Oxyacetylene Welding
 - i. RG45 - 3/32-inch - 1/8-inch diameter
- d. Cutting and Welding Tip Sizes:
 1. Oxyacetylene Cutting
 - i. Cutting tip sizes: 0 - 1 (Victor or Harris equipment)
 - ii. Welding tip sizes: 0 - 3 (Victor or Harris equipment)
 - iii. Equipment
 - (i) CC/CV machines
 - (ii) GMAW - CV only
 - (iii) SMAW - CC
 - (iv) GTAW- CC

SkillsUSA Michigan Welding Competition
High School: April 1st, 2022, Washtenaw Community College, Ann Arbor

The following is the contest meeting times and places for Secondary Welders at Washtenaw Community College Welding Lab on Friday April 1st, 2022. **Anyone who is not on time forfeits that time allotment.**

Friday April 1st, 2022 - Performance Test Schedule

Time	Location	Description
7:30am - 8:30am	Occupational Education Building	Arrival
8:30am - 9:00am	Various Rooms	Orientation
9:00am – 1:00pm	Welding Lab	Welding Contests

Lunch on own

I = Individual Competition
 O = Overall Competition

Note:

Your Contest numbers must be visible at all times and will be checked at your scheduled contestant's times. If you miss the time of your contest you might not be allowed to compete in the event.

Test Schedule

**The SkillsUSA Leadership Test will be administered online beginning March 23rd.
Please have the test completed before the competition date.**

Revised 3/08/222

I = Individual Competition
O = Overall Competition

Competitor Number	
-------------------	--

OVERALL

Max Mark	Mark Awarded
----------	--------------

Welds are placed properly according to print (refer to locations of E6010, E7018 welds and GMAW as specified by blueprint)				
1 defect = 20 points	3 defects = 14 points	5 or greater= 0 points	25	
2 defects = 17 points	4 defects = 11 points			
Project is free of Smoke and spatter 99% free of both.				
Yes/no			25	
Project is free of arc strikes				
1 defect = 20 points	3 defects = 14 points	5 or greater= 0 points	25	
2 defects = 17 points	4 defects = 11 points			
Weld Joints are free of undercut. Greater in depth than 1/32" equals one defect (Less than or equal to 1/8" in length = one defect)				
1 defect = 65 points	3 defects = 45 points	5 defects = 35 points	75	
2 defects = 55 points	4 defects = 40 points	6 or greater = 0 points		
Weld craters are properly filled through cross section. Yes/no				
1 defect = 25 points	3+ defects = 0 points		50	
2 defects = 10 points				
All welds free from Porosity (Less than or equal to 1/4" Dia. Cluster in any direction = one defect) (Any one more exceeding 3/32" in diameter = one defect)				
1 defect = 65 points	3 defects = 45 points	5 defects = 35 points	75	
2 defects = 55 points	4 defects = 40 points	6 or greater = 0 points		
Fillet weld legs are in accordance to with specifications (-0+1/16") (Length of defect Less than or equal to 1/8"= one defect)				
1 defect = 65 points	3 defects = 45 points	5 defects = 35 points	75	
2 defects = 55 points	4 defects = 40 points	6 or greater = 0 points		
All butt welds display complete joint penetration (Length of defect Less than or equal to 1/8" = one defect)				
1 defect = 40 points	3 defects = 25 points	5 defects = 15 Points	50	
2 defects = 30 points	4 defects = 20 points	6 or greater = 0 points		
All butt joints display proper face and root reinforcement. (Greater than or equal to 1/8" equals one defect) (Length of defect less than or equal to 1/8" equals one defect)				
1 defect = 40 points	3 defects = 25 points	5 defects = 15 Points	50	
2 defects = 30 points	4 defects = 20 points	6 or greater = 0 points		
Correct measurements according to print (Any discontinuity greater than or equal to 1/32" = 1 defect.				
Yes = 25 Points			25	
No= 0 points				
Properly wrapped all corners (Weld continuity and and fusion is maintained through the full radius of the corner.)				
Yes = 30 Points			30	
No= 0 points				
Safety violations				
Yes = -50 points			Minus 50 points	
No= 0				
			500	0

Signature Judge 1	_____
Signature Judge 2	_____

Aluminum

			Max Mark	Mark Awarded
Aluminum Project is free from Touchdowns				
1 defect = 55 points	3 defects = 35 points	5 defects = 15 points	65	
2 defects = 45 points	4 defects = 25 points	6 or more defects = 0 points		
Butt welded joints free from underfill. Any Visible discontinuity greater than 1/8" in length = 1 defect.)				
1 defect = 30 points	3+ defects = 0 points		40	
2 defects = 15 points				
Weld Joints are completely welded, and display full craters.				
1 defect = 35 points	3 defects = 25 points	5 defects = 10 Points	40	
2 defects = 30 points	4 defects = 15 points	6 or greater = 0 points		
All Fillet welds that do not call for melt through are free from burn through or melt through (Any indication less than or equal to 1/8" in length = one defect)				
1 defect = 55 points	3 defects = 35 points	5 defects = 15 points	65	
2 defects = 45 points	4 defects = 25 points	6 or more defects = 0 points		
Fillet weld legs are in accordance to specifications (-0+1/16") Length of discontinuity Less than or equal to 1/8" = one defect)				
1 defect = 35 points	3 defects = 25 points	5 defects = 10 Points	40	
2 defects = 30 points	4 defects = 15 points	6 or greater = 0 points		
All welds labled for melt through display full root fusion (Length of defect Less than or equal to 1/8" = one defect)				
1 defect = 60 points	3 defects = 30 points	5 defects = 10 Points	70	
2 defects = 50 points	4 defects = 20 points	6 or greater = 0 points		
All butt joints display proper face and root reinforcement. (Greater than or equal to 3/32" equals one defect) (Length of discontinuity less than or equal to 1/8" equals one defect)				
1 defect = 35 points	3 defects = 25 points	5 defects = 10 Points	40	
2 defects = 30 points	4 defects = 15 points	6 or greater = 0 points		
Correct measurements according to print (Any disconcontinuity greater than or equal to 1/32" = 1 defect. Length of discontinuity less than or equal to 1/8" = one defect)				
1 defect = 20 points	3+ defects = 0		40	
2 defects = 10 points				
Safety violations				
Yes = -50 points			Minus 50 points	
No= 0				
			400	0
Signature Judge 1				
Signature Judge 2				

OFC

			Max Mark	Mark Awarded
Line is cut to proper dimensions according to print. (Any discontinuity greater than or equal to 1/32" = 1 defect. Length of discontinuity less than or equal to 1/8" = one defect)				
1 defect = 30 points	3+ defects = 0		50	
2 defects = 10 points				
Line is cut to proper angle (Any discontinuity less than or equal to 5 degrees = 1 defect.)				
1 defect = 30 points	3+ defects = 0		40	
2 defects = 10 points				

Resume

Competitor Resume (Yes/No)				
Yes = 10 points			10	
No= 0 points				

Total Score				
Signature Judge 1			1000	0
Signature Judge 2				

Competitor Number	
-------------------	--

GMAW

Max Mark	Mark Awarded
----------	--------------

Project is free from wire whiskers (Each Wire whiskers equals one defect)				
1 defect = 40 points	3 defects = 20 points	5 or greater= 0 points	50	
2 defects = 30 points	4 defects = 10 points			
Project is free of Smoke and spatter 99% free of both.				
Yes/no			50	
Project is free of arc strikes				
1 defect = 40 points	3 defects = 20 points	5 defects = 0 points	50	
2 defects = 30 points	4 defects = 10 points			
Weld Joints are free of undercut. Greater in depth than 1/32" equals one defect (Less than or equal to 1/8" in length = one defect)				
1 defect = 130 points	3 defects = 90 points	5 defects = 50 points	150	
2 defects = 110 points	4 defects = 70 points	6 or greater = 0 points		
Weld craters are properly filled through cross section. Yes/no				
1 defect = 50 points	3+ defects = 0 points		100	
2 defects = 30 points				
All welds free from Porosity (Less than or equal to 1/4" Dia. Cluster in any direction = one defect) (Any one more exceeding 3/32" in diameter = one defect)				
1 defect = 130 points	3 defects = 90 points	5 defects = 50 points	150	
2 defects = 110 points	4 defects = 70 points	6 or greater = 0 points		
Fillet weld legs are in accordance to with specifications (-0+1/16") (Length of defect Less than or equal to 1/8"= one defect)				
1 defect = 130 points	3 defect = 90 points	5 defects = 50 points	150	
2 defect = 110 points	4 defects = 70 points	6 or greater = 0 points		
All butt welds display complete joint penetration (Length of defect Less than or equal to 1/8" = one defect)				
1 defect = 90 points	3 defects = 70 points	5 defects = 50 Points	100	
2 defects = 80 points	4 defects = 60 points	6 or greater = 0 points		
All butt joints display proper face and root reinforcement. (Greater than or equal to 1/8" equals one defect) (Length of defect less than or equal to 1/8" equals one defect)				
1 defect = 90 points	3 defects = 70 points	5 defects = 50 Points	100	
2 defects = 80 points	4 defects = 60 points	6 or greater = 0 points		
Correct measurements according to print				
Yes = 50 Points			50	
No= 0 points				
Properly wrapped all corners (Weld continuity and and fusion is maintained through the full radius of the corner.)				
Yes = 40 Points			40	
No= 0 points				
Competitor Resume				
Yes = 10 Points			10	
No= 0 points				
Safety violations				
Yes = -50 points			Minus 50 points	
No= 0				

1000	0
------	---

Signature Judge 1	
Signature Judge 2	

Competitor Number	
-------------------	--

SMAW

Max Mark	Mark Awarded
----------	--------------

Welds are placed properly according to print (refer to locations of E6010 and E7018 welds as specified by blueprint)				
1 defect = 40 points	3 defects = 20 points	5 or greater= 0 points	50	
2 defects = 30 points	4 defects = 10 points			
Project is free of Smoke and spatter 99% free of both.				
Yes/no			50	
Project is free of arc strikes				
1 defect = 40 points	3 defects = 20 points	5 defects = 0 points	50	
2 defects = 30 points	4 defects = 10 points			
Weld Joints are free of undercut. Greater in depth than 1/32" equals one defect (Less than or equal to 1/8" in length = one defect)				
1 defect = 130 points	3 defects = 90 points	5 defects = 50 points	150	
2 defects = 110 points	4 defects = 70 points	6 or greater = 0 points		
Weld craters are properly filled through cross section. Yes/no				
1 defect = 50 points	3+ defects = 0 points		100	
2 defects = 30 points				
All welds free from Porosity (Less than or equal to 1/4" Dia. Cluster in any direction = one defect) (Any one more exceeding 3/32" in diameter = one defect)				
1 defect = 130 points	3 defects = 90 points	5 defects = 50 points	150	
2 defects = 110 points	4 defects = 70 points	6 or greater = 0 points		
Fillet weld legs are in accordance to with specifications (-0+1/16") (Length of defect Less than or equal to 1/8"= one defect)				
1 defect = 130 points	3 defect = 90 points	5 defects = 50 points	150	
2 defect = 110 points	4 defects = 70 points	6 or greater = 0 points		
All butt welds display complete joint penetration (Length of defect Less than or equal to 1/8" = one defect)				
1 defect = 90 points	3 defects = 70 points	5 defects = 50 Points	100	
2 defects = 80 points	4 defects = 60 points	6 or greater = 0 points		
All butt joints display proper face and root reinforcement. (Greater than or equal to 1/8" equals one defect) (Length of defect less than or equal to 1/8" equals one defect)				
1 defect = 90 points	3 defects = 70 points	5 defects = 50 Points	100	
2 defects = 80 points	4 defects = 60 points	6 or greater = 0 points		
Correct measurements according to print				
Yes = 50 Points			50	
No= 0 points				
Properly wrapped all corners (Weld continuity and and fusion is maintained through the full radius of the corner.)				
Yes = 40 Points			40	
No= 0 points				
Competitor Resume				
Yes = 10 Points			10	
No= 0 points				
Safety violations				
Yes = -50 points			Minus 50 points	
No= 0				

1000	
------	--

Signature Judge 1	
Signature Judge 2	

Competitor Number	
-------------------	--

Aluminum

			Max Mark	Mark Awarded
Aluminum Project is free from Touchdowns				
1 defect = 130 points	3 defects = 70 points	5 defects = 10 points	150	
2 defects = 100 points	4 defects = 40 points	6 or more defects = 0 points		
Butt welded joints free from underfill. Any Visible discontinuity greater than 1/8" in length = 1 defect.)				
1 defect = 50 points	3+ defects = 0 points		100	
2 defects = 30 points				
Weld Joints are completely welded, and display full craters.				
1 defect = 90 points	3 defects = 70 points	5 defects = 50 Points	100	
2 defects = 80 points	4 defects = 60 points	6 or greater = 0 points		
All Fillet welds that do not call for melt through are free from burn through or melt through (Any indication less than or equal to 1/8" in length = one defect)				
1 defect = 130 points	3 defects = 90 points	5 defects = 50 Points	150	
2 defects = 110 points	4 defects = 70 points	6 or greater = 0 points		
Fillet weld legs are in accordance to specifications (-0+1/16") Length of discontinuity Less than or equal to 1/8" = one defect)				
1 defects = 90 points	3 defects = 50 points	5 defects = 1 Points	100	
2 defects = 70 points	4 defects = 30 points	6 or greater = 0 points		
All welds labled for melt through display full root fusion (Length of defect Less than or equal to 1/8" = one defect)				
1 defect = 150 points	3 defects = 100 points	5 defects = 50 Points	200	
2 defects = 130 points	4 defects = 70 points	6 or greater = 0 points		
All butt joints display proper face and root reinforcement. (Greater than or equal to 3/32" equals one defect) (Length of discontinuity less than or equal to 1/8" equals one defect)				
1 defects = 90 points	3 defects = 70 points	5 defects = 50 Points	100	
2 defects = 80 points	4 defects = 60 points	6 or greater = 0 points		
Correct measurements according to print (Any disconcontinuity greater than or equal to 1/32" = 1 defect				
1 defect = 60 points	3+ defects = 0		90	
2 defects = 30 points				
Safety violations				
Yes = -5 points			Minus 5 points	
No= 0				
Competitor Resume (Yes/No)				
Yes = 10 points			10	
No= 0 points				
			1000	0

Signature Judge 1		
Signature Judge 2		

Competitor Number	
-------------------	--

OFW

	Max Mark	Mark Awarded
Weld Joints are free of undercut. Greater in depth than 1/32" equals one defect (Less than or equal to 1/8" in length = one defect)		
1 defect = 90 points 3 defects = 70 points 5 defects = 30 Points	100 Point	
2 defects = 80 points 4 defects = 50 points 6 or greater = 0 points		
Weld Joints are completely welded, and craters are filled through cross section		
1 defect = 90 points 3 defects = 70 points 5 defects = 30 Points	100 points	
2 defects = 80 points 4 defects = 50 points 6 or greater = 0 points		
All Fillet welds that do not call for melt through are free from burn through or melt through (Any indication less than or equal to 1/8" in length = one defect)		
1 defect = 90 points 3 defects = 70 points 5 defects = 30 Points	100 points	
2 defects = 80 points 4 defects = 50 points 6 or greater = 0 points		
Fillet weld legs are in accordance to specifications (-0+1/16") (Length of defect Less than or equal to 1/8" = one defect)		
1 defect = 90 points 3 defects = 70 points 5 defects = 30 Points	100 points	
2 defects = 80 points 4 defects = 50 points 6 or greater = 0 points		
All welds labled for melt through display full root fusion (Length of defect Less than or equal to 1/8" = one defect)		
1 defect = 180 points 3 defects = 100 points 5 defects = 30 Points	200 points	
2 defects = 140 points 4 defects = 70 points 6 or greater = 0 points		
Correct measurements according to print		
1 defect = 60 points 3+ defects = 0	100 points	
2 defects = 30 points		
All butt joints display proper face and root reinforcement. (Greater than or equal to 1/16" equals one defect) (Length of defect less than or equal to 1/8" equals one defect)		
1 defect = 170 points 3 defects = 120 points 5 defects = 50 Points	190 points	
2 defects = 150 points 4 defects = 100 points 6 or greater = 0 points		
Butt welded plates are free from missalignment. (greater than or equal to 1/16 of missalignment. Length of defect less than or equal 1/8" = one defect)		
1 defect = 90 points 3 defects = 70 points 5 defects = 30 Points	100 points	
2 defects = 80 points 4 defects = 50 points 6 or greater = 0 points		
Competitor Resume (Yes/No)		
Yes = 10 points	10 points	
No= 0 points		
Safety violations		
Yes = -50 points	Minus 50 points	
No= 0		
Total Score (1000)		0

Signature Judge 1	
Signature Judge 2	